

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NYD980532071	2. Page 1 of 1	3. Emergency Response Phone (203) 238-6745	4. Manifest Tracking Number 009528662 JJK		
5. Generator's Name and Mailing Address Brooklyn Union Gas One Metrotech Plaza Brooklyn, NY 11201 Generator's Phone: 718 9625412				Generator's Site Address (if different than mailing address) Clifton MPG Site 25 Willow Ave Staten Island, NY 10305			
6. Transporter 1 Company Name UNITED INDUSTRIAL SERVICES					U.S. EPA ID Number CTD021816889		
7. Transporter 2 Company Name					U.S. EPA ID Number		
8. Designated Facility Name and Site Address BRIDGEPORT UNITED RECYCLING 50 CROSS STREET BRIDGEPORT, CT 06610 Facility's Phone: 203 2241666					U.S. EPA ID Number CTD002593887		
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
		No.	Type				
X	1. HA3082, HAZARDOUS WASTE, LIQUID, N.O.S., 9, PGIII, RQ	001	TT	5000	G	D018	
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information 1) F120610002BZ - EMERGENCY RESPONSE GUIDE # 171 EMERGENCY PH# (203) 238-6745							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offorer's Printed/Typed Name Ed Miller				Signature <i>[Signature]</i>		Month Day Year 11 26 12	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Peter DiPalma				Signature <i>[Signature]</i>		Month Day Year 01 26 12	
Transporter 2 Printed/Typed Name				Signature		Month Day Year	
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator) U.S. EPA ID Number							
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H135		2.		3.		4.	
20. Designated Facility Owner or Operator Certification of receipt of hazardous materials covered by the manifest except as noted in Item 8a				Signature <i>[Signature]</i>		Month Day Year 11 26 12	
Printed/Typed Name Solee Burgos							