

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NYD980532071		2. Page 1 of 1		3. Emergency Response Phone (203) 238-6745		4. Manifest Tracking Number 009528661 JJK							
		5. Generator's Name and Mailing Address Brooklyn Union Gas One Metrotech Plaza Brooklyn, NY 11201 Generator's Phone: 718 9635412						Generator's Site Address (if different than mailing address) Clifton MPG Site 25 Willow Ave Staten Island, NY 10305							
GENERATOR		6. Transporter 1 Company Name UNITED INDUSTRIAL SERVICES						U.S. EPA ID Number CTD021816889							
		7. Transporter 2 Company Name						U.S. EPA ID Number							
DESIGNATED FACILITY		8. Designated Facility Name and Site Address BRIDGEPORT UNITED RECYCLING 50 CROSS STREET BRIDGEPORT, CT 06610 Facility's Phone: 203 2241666						U.S. EPA ID Number CTD002593887							
		9a. HM						9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers No. Type		11. Total Quantity		12. Unit Wt./Vol.	
TRANSPORTER		INTL		X		HA3082, HAZARDOUS WASTE, LIQUID, N.O.S., 9, PGIII, RQ		001 TT		1500g		G		D018	
14. Special Handling Instructions and Additional Information 1) F120610002BZ - EMERGENCY RESPONSE GUIDE # 171 EMERGENCY PH# (203) 238-6745															
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Officer's Printed/Typed Name E.D. Miller															
Signature <i>[Signature]</i> Agent For Brooklyn Union Gas															
Month Day Year 01 26 12															
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:															
17. Transporter Acknowledgment of Receipt of Materials															
Transporter 1 Printed/Typed Name Jim Dery															
Signature <i>[Signature]</i>															
Month Day Year 01 26 12															
Transporter 2 Printed/Typed Name															
Signature															
Month Day Year															
18. Discrepancy															
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection															
Manifest Reference Number:															
18b. Alternate Facility (or Generator) U.S. EPA ID Number															
Facility's Phone:															
18c. Signature of Alternate Facility (or Generator) Month Day Year															
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)															
1. H135 2. 3. 4.															
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a															
Printed/Typed Name STEPHEN DUBAUSKAS															
Signature <i>[Signature]</i> Stephen Dubauskas															
Month Day Year 01 26 12															