

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>CT0983870593</b>		2. Page 1 of <b>1</b>		3. Emergency Response Phone <b>200-424-9300</b>		4. Manifest Tracking Number <b>000906065 JJK</b>							
		5. Generator's Name and Mailing Address <b>Yale University PO Box 208112 New Haven, CT 06520-8112</b>						Generator's Site Address (if different than mailing address) <b>Yale University 268 Whitney Avenue New Haven, CT 06511-2902</b>							
6. Transporter 1 Company Name <b>R+R Trucking</b>		U.S. EPA ID Number <b>MDR000501973</b>													
7. Transporter 2 Company Name		U.S. EPA ID Number													
8. Designated Facility Name and Site Address <b>NSSI 5709 Etheridge Street Houston, TX 77087</b>		U.S. EPA ID Number <b>TX0982560294</b>													
9a. HM		9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers No. Type		11. Total Quantity		12. Unit Wt./Vol.		13. Waste Codes			
1. <b>X</b>		1. <b>Waste Corrosive Liquids, n.d.s. (contains 59% Nitric Acid), 8, UN1760, PG II</b>				1 <b>DM</b>		45 <b>K</b>				0002			
2.															
3.															
4.															
14. Special Handling Instructions and Additional Information <b>9b.1. Bulk Liquid Ref. ERE No. 154 Ref. NRC Manifest No. 0019-100306 NSSI-1</b>															
15. <b>GENERATOR'S/OFFEROR'S CERTIFICATION:</b> I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Officer's Printed/Typed Name <b>JAMES WATKINS</b>						Signature <i>[Signature]</i>				Month Day Year <b>10 3 06</b>					
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____															
17. Transporter Acknowledgment of Receipt of Materials															
Transporter 1 Printed/Typed Name <b>Tyson Rogers</b>						Signature <i>[Signature]</i>				Month Day Year <b>10 03 06</b>					
Transporter 2 Printed/Typed Name						Signature				Month Day Year					
18. Discrepancy															
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection															
Manifest Reference Number: _____															
18b. Alternate Facility (or Generator) U.S. EPA ID Number															
Facility's Phone: _____															
18c. Signature of Alternate Facility (or Generator) Month Day Year															
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)															
1.				2.				3.				4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a															
Printed/Typed Name						Signature				Month Day Year					