

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number MAC300000759	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 005594351 FLE	
5. Generator's Name and Mailing Address Checon Corporation 30 Larsen Way Attleboro Falls, MA 02763			Generator's Site Address (if different than mailing address) SAME			
Generator's Phone: (508) 808-5138						
6. Transporter 1 Company Name Clean Harbors Environmental Services Inc			U.S. EPA ID Number MAD039322250			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Harbors of Connecticut Inc 51 Broderick Road Bristol, CT 06010			U.S. EPA ID Number CTD000604488			
Facility's Phone: (860) 583-8917						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
x	1. RQ, NA3082, HAZARDOUS WASTE, LIQUID, N.O.S., (CADMIUM), 9, PG III (D006)	001 TT 3800 G				D006 D011
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information 1. CH465786B ERG#171						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name Pargu Geoffroy		Signature Pargu Geoffroy		Month Day Year 09/10/12		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of export: Transporter signature (for exports only): Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name John A. Russell Signature John A. Russell Month Day Year 09/10/12 Transporter 2 Printed/Typed Name Signature Month Day Year						
18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H077 2. 3. 4.						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Denise Bufal Signature Denise Bufal Month Day Year 9/10/12						

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

Clean Harbors has the appropriate permits for and will accept the waste the generator is shipping.